

WSM

WORKSHOP MANUAL
TRACTOR

M100X,M110X,M126X,M135X

Kubota

TO THE READER

This Workshop Manual tells the servicing personnel about the mechanism, servicing and maintenance of the M100X, M110X, M126X and M135X. It contains 4 parts: "**Information**", "**General**", "**Mechanism**" and "**Servicing**".

■ Information

This section primarily contains information below.

- Safety First
- Safety Decal
- Specification
- Dimension

■ General

This section primarily contains information below.

- Engine Identification
- Model Identification
- General Precautions
- Maintenance Check List
- Check and Maintenance
- Special Tools

■ Mechanism

This section contains information on the structure and the function of the unit. Before you continue with the subsequent sections, make sure that you read this section.

Refer to the latest version of Workshop Manual (Code No. 9Y021-01870 / 9Y021-18200) for the diesel engine / tractor mechanism that this workshop manual does not include.

■ Servicing

This section primarily contains information below.

- Troubleshooting
- Servicing Specifications
- Tightening Torques
- Checking, Disassembling and Servicing

Regarding the servicing of Common Rail System (CRS), refer to "DIAGNOSIS MANUAL (CD-ROM)" (9Y130-00142, 9Y130-00531) at the end of this manual.

All illustrations, photographs and specifications contained in this manual are of the newest information available at the time of publication.

KUBOTA reserves the right to change all information at any time without notice.

Since this manual includes many models, information or illustrations and photographs can show more than one model.

© KUBOTA Corporation 2010

September 2010

Record of Revisions

For pdf, use search function {Search word} to find all the revised locations.

Last digit of the Code No.	Month of Revision	Main Revised Point and Corrective Measures {Search word}	Reference Page
9Y121-23560	2020.03	The code number of this WSM has been changed from 9Y121-05259 to 9Y121-23560.	—
		Additional information <ul style="list-style-type: none">Diagnostic trouble code was changed.	9-S21
		Corrected information <ul style="list-style-type: none">Instruction for "Calibration of solenoid proportional pressure reducing valve (Master, Main shift L and H)" is corrected.	9-S44
1	2022.01	Update of Air-conditioner belt tension	G-19, G-35 to G-36, 1-S9, 1-S21, 1-S30, 2-S8, 2-S16, 10-S6, 10-S38
		Additional, deleted and changed information <ul style="list-style-type: none">Minor correction about cylinder head gasket shape.Relief valve assembly topic is deleted because this assy isn't permitted to disassemble.	1-S14, 1-S44, 1-S46 8-S41

I INFORMATION

INFORMATION

CONTENTS

1. SAFETY FIRST	I-1
2. SAFETY DECALS	I-4
3. SPECIFICATIONS.....	I-11
4. TRAVELING SPEEDS.....	I-12
5. DIMENSIONS	I-13

It's a preview. You can download the full file by clicking the link below.

<https://shopservicemanual.com/>

Service Manuals from 2\$