


**Dozer
96 Inch**



Bobcat®

Service Manual

(96 Inch) S/N 224400101 & Above



Doosan purchased Bobcat Company from Ingersoll-Rand Company in 2007. Any reference to Ingersoll-Rand Company or use of trademarks, service marks, logos, or other proprietary identifying marks belonging to Ingersoll-Rand Company in this manual is historical or nominative in nature, and is not meant to suggest a current affiliation between Ingersoll-Rand Company and Bobcat Company or the products of either.

ALPHABETICAL INDEX

ACD (ATTACHMENT CONTROL DEVICE)	30-10-1
ATTACHMENT DELIVERY REPORT	III
CUTTING EDGE	30-40-1
ELECTRICAL SCHEMATIC-7 PIN CONNECTOR	SPEC-20-1
ELECTRICAL SCHEMATIC-7 PIN CONNECTOR WITH 14 PIN ADAPTER HARNESS	SPEC-20-1
HYDRAULIC CONTROL VALVE	20-10-1
HYDRAULIC CYLINDER	20-20-1
HYDRAULIC SCHEMATIC	SPEC-30-1
INSPECTION	10-20-1
IDENTIFICATION	IV
MOLDBOARD	30-20-1
MOUNTING FRAME AND ROTATING SECTION	30-30-1
LUBRICATION	10-40-1
SERIAL NUMBER LOCATION	III
SPECIFICATIONS	SPEC-10-1
TROUBLESHOOTING	10-10-1



Bobcat®

CONTENTS

**SAFETY AND
MAINTENANCE**

**HYDRAULIC
SYSTEM**

**MAIN
FRAME**

**SPECIFICATIONS
AND
SCHEMATICS**

ATTACHMENT DELIVERY REPORT	III
IDENTIFICATION AND MACHINE SIGNS (DECALS)	IV
SERIAL NUMBER LOCATION	III
SAFETY AND MAINTENANCE.....	10-01
HYDRAULIC SYSTEM	20-01
MAIN FRAME	30-01
SPECIFICATIONS AND SCHEMATICS	SPEC-01

CALIFORNIA

PROPOSITION 65 WARNING

Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects and other reproductive harm.

It's a preview. You can download the full file by clicking the link below.

<https://shop servicemanual.com/>

Service Manuals from 2\$