

SERVICE MANUAL

T7.290 AutoCommand™

T7.315 AutoCommand™

TIER 4B (FINAL)

Tractor

PIN ZFEA01001 and above

Part number 48193177

English

November 2017





SERVICE MANUAL

T7.290 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931], T7.290 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528], T7.290 AutoCommand™ Sidewinder II [ZGEA04529 -], T7.315 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931], T7.315 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528], T7.315 AutoCommand™ Sidewinder II [ZGEA04529 -]

Link Product / Engine

Product	Market Product	Engine
T7.290 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931]	Middle East Africa	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931]	Australia New Zealand	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931]	Asia Pacific	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528]	Asia Pacific	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528]	Australia New Zealand	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528]	Middle East Africa	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZGEA04529 -]	Middle East Africa	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZGEA04529 -]	Australia New Zealand	F4DFE617M*B001
T7.290 AutoCommand™ Sidewinder II [ZGEA04529 -]	Asia Pacific	F4DFE617M*B001
T7.315 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931]	Asia Pacific	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931]	Australia New Zealand	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZFEA01001 - ZGEA02931]	Middle East Africa	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528]	Asia Pacific	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528]	Australia New Zealand	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZGEA02932 - ZGEA04528]	Middle East Africa	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZGEA04529 -]	Australia New Zealand	F4DFE617L*B002

Product	Market Product	Engine
T7.315 AutoCommand™ Sidewinder II [ZGEA04529 -]	Middle East Africa	F4DFE617L*B002
T7.315 AutoCommand™ Sidewinder II [ZGEA04529 -]	Asia Pacific	F4DFE617L*B002

Contents

INTRODUCTION

Engine.....	10
[10.001] Engine and crankcase	10.1
[10.216] Fuel tanks	10.2
[10.202] Air cleaners and lines	10.3
[10.254] Intake and exhaust manifolds and muffler	10.4
[10.500] Selective Catalytic Reduction (SCR) exhaust treatment	10.5
[10.400] Engine cooling system	10.6
[10.414] Fan and drive	10.7
[10.310] Aftercooler.....	10.8
Clutch	18
[18.112] Slip clutch or flywheel damper	18.1
Transmission.....	21
[21.504] Continuously Variable Transmission (CVT)	21.1
[21.505] Continuously Variable Transmission (CVT) external controls.....	21.2
[21.506] Continuously Variable Transmission (CVT) hydraulic components	21.3
[21.507] Continuously Variable Transmission (CVT) internal components.....	21.4
Four-Wheel Drive (4WD) system	23
[23.202] Electro-hydraulic control	23.1
[23.314] Drive shaft.....	23.2
Front axle system	25
[25.100] Powered front axle	25.1
[25.102] Front bevel gear set and differential	25.2
[25.108] Final drive hub, steering knuckles, and shafts	25.3
[25.122] Axle suspension control.....	25.4
Rear axle system.....	27

It's a preview. You can download the full file by clicking the link below.

<https://shopservicemanual.com/>

Service Manuals from 2\$