

# SERVICE MANUAL

**P2080 / P2085**

**Disk Drill**

**Part number 47648338**

2<sup>nd</sup> edition English

June 2014

*Replaces part number 47484215*



# Contents

---

## INTRODUCTION

Front axle system .....	25
[25.400] Non-powered front axle .....	25.1
Rear axle system.....	27
[27.550] Non-powered rear axle.....	27.1
Hydraulic systems.....	35
[35.744] Seeding hydraulic circuit .....	35.1
[35.912] Hydraulic seeding fan system.....	35.2
[35.946] Frame positioning lifting.....	35.3
Wheels .....	44
[44.511] Front wheels.....	44.1
Electrical systems .....	55
[55.000] Electrical system .....	55.1
[55.100] Harnesses and connectors.....	55.2
[55.511] Light harnesses .....	55.3
[55.516] Seeding control system .....	55.4
[55.517] Cab seeding controls.....	55.5
[55.640] Electronic modules.....	55.6
[55.DTC] FAULT CODES.....	55.7
Metering system .....	61
[61.904] Product metering .....	61.1
Seeding.....	77
[77.100] Product handling and delivery drive system .....	77.1
[77.101] Seeding fan system .....	77.2
[77.105] Seeding tool.....	77.3

[77.904] Air distribution system..... 77.4





# INTRODUCTION

It's a preview. You can download the full file by clicking the link below.

<https://shopservicemanual.com/>

Service Manuals from 2\$